Foston and Scropton Parish Council in South Derbyshire Alison Barnes- Parish Clerk & Treasurer

4 Lodge Hill, Tutbury, Burton Upon Trent, DE13 9HF Telephone 07967 385862

PARISH HALL RISK ASSESMENT 2020-2021

Date Updated: June 2020

Dear Councillors,

The Council is expected to carry out an annual risk assessment of Parish Hall risks it is exposed to and identify any actions it considers necessary to minimise those risks.

Definition of Risk Management

Risk is the threat that an event or action will adversely affect an organisation's ability to achieve its objectives and to successfully execute its strategies. Risk management is the process by which risks are identified, evaluated and controlled. It is a key element of the framework of governance together with community focus, structures and processes, standards of conduct and service delivery arrangements. Audit Commission – Worth the Risk: Improving Risk Management in Local Government (2001:5)

This document has been produced to enable the Parish Council to assess the risks that it faces and satisfy itself that it has taken adequate steps to minimise them. The Council is aware that although some risks can never be eliminated fully, it has in place a strategy that provides a structured, systematic and focused approach to managing risk. The list is not exhaustive and Council may wish to consider other risks not identified.

The table below shows general risks that the Parish Council could consider:

Subject - Identifies the subject Risks Identified - Identifies what the risk may be Risk Score- Identifies the level of risk Management/ Risk Control - Evaluates the management and control of the risk and records findings Review Date / Responsibilities - Reviews, assesses and revises procedures if required

This document was approved by the Parish Council at the meeting held on Tuesday 9th June 2020 (Minute Number 34/20)

Yours Faithfully

Subject	Risk(s) Identified	Risk Score	Management/Control of Risk	Review Date / Reassessment
		H/M/L		
Slips, Trips, Falls	Users of the hall may incur	L	Spillages to be cleaned up immediately.	Adequate Risk Control In Place
	bruising, cuts, fractures		 Heating to ensure floor is dry. 	
			Floor to main hall is carpeted- Should help	
			Mats are suitable placed to stop rain water	
			being carried into hall	
			No storage in walkways	
			Inform all users	
			When appropriate to ensure all areas are free	
			from hazards	
Working At Height	Anyone working at hall may	L	Two people to use ladder at any one time	Monitor use re; need for possible
	suffer bruising, dislocation,		Two people will always be present when	training
	fracture		ladder in use. Ladder locked in store.	
Stored Equipment	Users could be injured by	L	All stored equipment other than furniture	Adequate Risk Control In Place
	falling stacks/stored		is in the store.	
	equipment		Details included in hiring agreement issued	
			to every hirer	
Manual Handling	Back injury by lifting heavy	M	All tables to be lifted by two people	Parish Council to review possibility of
	objects		Inform Hirers	folding tables
Hazardous Substances	Skin infections	L	Cleaning equipment stored in locked	Adequate Risk Control In Place
	Breathing problems		cupboards	
			Mops, buckets provided	
			Cleaning	
			Cleaning equipment to be kept in locked	
			filing cabinet in sand store.	
Car Park	Uneven surface and different	Н	Outside lighting and flood light recently	Road Planning Surface Installed Dec 2013-
	materials could cause trip/fall		installed to light the area.	Provides more solid base for users. Future
	hazard		Warning included in hiring agreement	plans to tarmac car park entirely subject to
				budget restrictions.
Legionnaires Disease	Individual using the hall	M	Survey completed by an outside company	Adequate Risk Control In Place

	catching Legionnaires disease		Cllr Groom trained As part of the hire conditions all taps to be run for 5 minutes and toilets flushed.	To be reviewed yearly
Asbestos	N/A	N/A	N/A	Building built in!! therefore no asbestos present
Carbon Monoxide	N/A	N/A	N/A	No gas present in the hall
Electrical Equipment	Shocks Fire	L	PAT testing to take place yearly Fire extinguishers tested yearly and replaced where necessary	Adequate Risk Control In Place